

# بِسْمِ اللّٰهِ الرَّحْمٰنِ الرَّحِیْمِ

## تئوری جامع ماشینهای الکتریکی

مدرس: دکتر عباس کتابی

مراجع درس:




- ☞ “Analysis of Electric Machinery and Drive Systems”, Third Edition, By: P. C. Krause, O. Wasynczuk and S. D. Sudhoff, IEEE Press, 2013.
- ☞ “Electromechanical Motion Devices”, Second Edition, By: P. C. Krause, O. Wasynczuk and S. Pekarek, Wiley-IEEE Press, 2012.
- ☞ “Dynamic simulation of Electric Machinery using MATLAB”, by: Chee-Mun Ong, Prentice Hall PTR, 1997

نحوه ارزشیابی:

تکالیف: 2 نمره

امتحان پایانترم: 13 نمره

پروژه: 5 نمره



## مطالب درس:

- Reference Frame Theory
- 3-Phase Induction Machines
- Synchronous Machines
- Machine Equations in Operational Impedances and Time Constants
- Linearized Machine Equations
- Reduced Order Machine Equations

# Reference Frame Theory

## ➤ Power of Reference Frame Theory:

- Eliminates Rotor Position Dependence inductances
- Transforms Nonlinear Systems to Linear Systems for Certain Cases
- Fundamental Tool For Development of Equivalent Circuits
- Can Be Used to Make AC Quantities Become DC Quantities
- Framework of Most Controllers



# Reference Frame Theory

## ➤ History of Reference Frame Theory

- 1929: Park's Transformation
  - ☞ Synchronous Machine; Rotor Reference Frame
- 1938: Stanley
  - ☞ Induction Machine; Stationary Reference Frame
- 1951: Kron
  - ☞ Induction Machine; Synchronous Reference Frame
- 1957: Brereton
  - ☞ Induction Machine; Rotor Reference Frame
- 1965: Krause
  - ☞ Arbitrary Reference Frame

# Arbitrary Reference Frame

- Consider stator winding of a 2-pole 3-phase symmetrical machine



# Arbitrary Reference Frame

- Synchronous and induction machine **inductances** are **functions of the rotor speed**, therefore the coefficients of the differential equations (voltage equations) which describe the behavior of these machines are **time-varying**.
- A change of variables can be used to reduce the complexity of machine differential equations, and represent these equations in another reference frame with **constant coefficients**.

# Arbitrary Reference Frame


- A change of variables which formulates a transformation of the 3-phase variables of stationary circuit elements to the arbitrary reference frame may be expressed

$$\mathbf{f}_{qd0s} = \mathbf{K}_s \mathbf{f}_{abcs}$$

$$\mathbf{K}_s = \frac{2}{3} \begin{bmatrix} \cos \theta & \cos(\theta - \frac{2\pi}{3}) & \cos(\theta + \frac{2\pi}{3}) \\ \sin \theta & \sin(\theta - \frac{2\pi}{3}) & \sin(\theta + \frac{2\pi}{3}) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix},$$

where,  $(\mathbf{f}_{qd0s})^T = [f_{qs} \quad f_{ds} \quad f_{0s}]$ ,

$$(\mathbf{f}_{abcs})^T = [f_{as} \quad f_{bs} \quad f_{cs}], \quad \theta = \int_0^t \omega(t) dt + \theta(0).$$




# Arbitrary Reference Frame

$$(\mathbf{K}_s)^{-1} = \begin{bmatrix} \cos \theta & \sin \theta & 1 \\ \cos(\theta - \frac{2\pi}{3}) & \sin(\theta - \frac{2\pi}{3}) & 1 \\ \cos(\theta + \frac{2\pi}{3}) & \sin(\theta + \frac{2\pi}{3}) & 1 \end{bmatrix}.$$

- “f” can represent either voltage, current, or flux linkage.
- “s” indicates the variables, parameters and transformation associated with stationary circuits.
- “ $\omega$ ” represent the speed of reference frame.



# Arbitrary Reference Frame



- $\omega=0$ : Stationary reference frame.
- $\omega=\omega_e$ : synchronously rotating reference frame.
- $\omega=\omega_r$ : rotor reference frame (i.e., the reference frame is fixed on the rotor).

# Arbitrary Reference Frame


- $f_{as}$ ,  $f_{bs}$  and  $f_{cs}$  may be thought of as the direction of the magnetic axes of the stator windings.
- $f_{qs}$  and  $f_{ds}$  can be considered as the direction of the magnetic axes of the “new” fictitious windings located on  $qs$  and  $ds$  axis which are created by the change of variables.
- Power Equations:

$$P_{abcs} = V_{as}i_{as} + V_{bs}i_{bs} + V_{cs}i_{cs}$$

$$P_{qd0s} = P_{abcs} = \frac{3}{2} (V_{qs}i_{qs} + V_{ds}i_{ds} + 2V_{0s}i_{0s})$$

# Arbitrary Reference Frame

- Stationary circuit variables transformed to the arbitrary reference frame.
- Resistive elements: For a 3-phase resistive circuit,



$$V_{abc s} = \bar{r}_s i_{abc s} \quad \bar{r}_s = \begin{bmatrix} r_s & 0 & 0 \\ 0 & r_s & 0 \\ 0 & 0 & r_s \end{bmatrix}$$

$$i_{abc s} = (\mathbf{K}_s)^{-1} i_{qd0s} \quad V_{abc s} = (\mathbf{K}_s)^{-1} V_{qd0s}$$


$$(\mathbf{K}_s)^{-1} V_{qd0s} = \bar{r}_s (\mathbf{K}_s)^{-1} i_{qd0s}$$

$$V_{qd0s} = (\mathbf{K}_s) \bar{r}_s (\mathbf{K}_s)^{-1} i_{qd0s} \quad , (\mathbf{K}_s) \bar{r}_s (\mathbf{K}_s)^{-1} = \bar{r}_s$$

$$V_{qd0s} = \bar{r}_s i_{qd0s}$$

# Arbitrary Reference Frame

- Inductive elements: For a 3-phase inductive circuit,



$$V_{abcs} = p\lambda_{abcs},$$

$$\text{where, } p = \frac{d}{dt},$$

$$\lambda_{abcs} = \mathbf{L}_s i_{abcs} = \begin{bmatrix} L_s & 0 & 0 \\ 0 & L_s & 0 \\ 0 & 0 & L_s \end{bmatrix} \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix}$$

# Arbitrary Reference Frame

- In terms of the substitute variables, we have

$$\mathbf{V}_{qd0s} = \mathbf{K}_s \cdot p[\mathbf{K}_s^{-1} \lambda_{qd0s}] = \mathbf{K}_s \cdot p[\mathbf{K}_s^{-1}] \lambda_{qd0s} + \mathbf{K}_s \cdot [\mathbf{K}_s^{-1}] p \lambda_{qd0s}$$

$$\text{where, } p[\mathbf{K}_s^{-1}] = \omega \cdot \begin{bmatrix} -\sin \theta & \cos \theta & 0 \\ -\sin(\theta - \frac{2\pi}{3}) & \cos(\theta - \frac{2\pi}{3}) & 0 \\ -\sin(\theta + \frac{2\pi}{3}) & \cos(\theta + \frac{2\pi}{3}) & 0 \end{bmatrix}$$

- After some work, we can show that

$$\mathbf{K}_s \cdot p[\mathbf{K}_s^{-1}] = \omega \cdot \begin{bmatrix} 0 & 1 & 0 \\ -1 & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix}$$

# Arbitrary Reference Frame

$$V_{qd0s} = \underbrace{\mathbf{K}_s p[(\mathbf{K}_s)^{-1}] \lambda_{qd0s}}_{\omega \lambda_{dqs}} + \underbrace{\mathbf{K}_s (\mathbf{K}_s)^{-1} p \lambda_{qd0s}}_{p \lambda_{qd0s}}$$

$$V_{qd0s} = \omega \lambda_{dqs} + p \lambda_{qd0s}$$

$$\text{where, } (\lambda_{dqs})^T = [\lambda_{ds} \quad -\lambda_{qs} \quad 0]$$

- Vector equation  $V_{qd0s}$  can be expressed as

$$V_{qs} = \omega \lambda_{ds} + p \lambda_{qs}$$

$$V_{ds} = -\omega \lambda_{qs} + p \lambda_{ds}$$

$$V_{0s} = p \lambda_{0s}$$

where “ $\omega \lambda_{ds}$ ” term and “ $\omega \lambda_{qs}$ ” term are referred to as a “speed voltage” with the speed being the angular velocity of the arbitrary reference frame.

# Arbitrary Reference Frame

- When the reference frame is fixed in the stator, that is, the stationary reference frame ( $\omega=0$ ), the voltage equations for the three-phase circuit become the familiar time rate of change of flux linkage in abcs reference frame
- For the three-phase circuit shown,  $\mathbf{L}_s$  is a diagonal matrix, and

$$\lambda_{abcs} = \mathbf{L}_s i_{abcs}$$

$$\lambda_{qd0s} = \mathbf{K}_s \mathbf{L}_s \mathbf{K}_s^{-1} i_{qd0s} = \mathbf{L}_s i_{qd0s}$$

# Arbitrary Reference Frame

- For the three-phase induction or synchronous machine,  $\mathbf{L}_s$  matrix is expressed as

$$\mathbf{L}_s = \begin{bmatrix} L_{ls} + L_{ms} & -\frac{1}{2}L_{ms} & -\frac{1}{2}L_{ms} \\ -\frac{1}{2}L_{ms} & L_{ls} + L_{ms} & -\frac{1}{2}L_{ms} \\ -\frac{1}{2}L_{ms} & -\frac{1}{2}L_{ms} & L_{ls} + L_{ms} \end{bmatrix}$$


where,  $L_{ls}$ : leakage inductance,  $L_{ms}$ : magnetizing inductance

$$\mathbf{K}_s \mathbf{L}_s (\mathbf{K}_s)^{-1} = \begin{bmatrix} L_{ls} + \frac{3}{2}L_{ms} & 0 & 0 \\ 0 & L_{ls} + \frac{3}{2}L_{ms} & 0 \\ 0 & 0 & L_{ls} \end{bmatrix}$$




# Arbitrary Reference Frame

- Consider the stator windings of a symmetrical induction or round rotor synchronous machine shown below



$$\mathbf{r}_s = \text{diag}[r_s \quad r_s \quad r_s]$$

$$\mathbf{L}_s = \begin{bmatrix} L_s & M & M \\ M & L_s & M \\ M & M & L_s \end{bmatrix} \quad \begin{aligned} L_s &= L_{ls} + L_{ms} \\ M &= -\frac{1}{2}L_{ms} \end{aligned}$$



# Arbitrary Reference Frame

- For each phase voltage, we write the following equations,

$$V_{as} = r_s i_{as} + p \lambda_{as}$$

$$V_{qd0s} = \mathbf{K}_s V_{abcs}$$

$$V_{bs} = r_s i_{bs} + p \lambda_{bs},$$

$$i_{qd0s} = \mathbf{K}_s i_{abcs}$$

$$V_{cs} = r_s i_{cs} + p \lambda_{cs}$$

$$\lambda_{qd0s} = \mathbf{K}_s \lambda_{abcs}$$

$$\lambda_{abcs} = \mathbf{L}_s i_{abcs}$$

- In vector form,

$$V_{abcs} = \mathbf{r}_s i_{abcs} + p \lambda_{abcs},$$

Multiplying by  $\mathbf{K}_s$

$$\mathbf{K}_s V_{abcs} = \mathbf{K}_s \mathbf{r}_s i_{abcs} + \mathbf{K}_s p \lambda_{abcs}$$

# Arbitrary Reference Frame

- Replace  $i_{abc_s}$  and  $\lambda_{abc_s}$  using the transformation equations,

$$\mathbf{K}_s V_{abc_s} = \mathbf{K}_s \mathbf{r}_s (\mathbf{K}_s^{-1} i_{qd0s}) + \mathbf{K}_s p (\mathbf{K}_s^{-1} \lambda_{qd0s})$$

$$V_{qd0s} = \mathbf{r}_s i_{qd0s} + \bar{\omega} \bar{\lambda}_{qd0s}$$

or

$$V_{qs} = r_s i_{qs} + \omega \lambda_{ds} + p \lambda_{qs}$$

$$V_{ds} = r_s i_{ds} - \omega \lambda_{qs} + p \lambda_{ds}$$

$$V_{0s} = r_s i_{0s} + p \lambda_{0s}$$

$$\mathbf{K}_s \mathbf{L}_s (\mathbf{K}_s)^{-1} = \begin{bmatrix} L_s - M & 0 & 0 \\ 0 & L_s - M & 0 \\ 0 & 0 & L_s + 2M \end{bmatrix}$$

$$\text{where, } \bar{\omega} = \omega \begin{bmatrix} 0 & 1 & 0 \\ -1 & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix}$$




$$\lambda_{qs} = (L_s - M) i_{qs}$$

$$\lambda_{ds} = (L_s - M) i_{ds}$$

$$\lambda_{0s} = (L_s + 2M) i_{0s}$$

# Commonly Used Reference Frames

- Our equivalent circuit in arbitrary reference frame can be represented as



Commonly used reference frame

# Commonly Used Reference Frames

- $\omega = \text{unspecified}$ : stationary circuit variables referred to the arbitrary reference frame. The variables are referred to as  $f_{qd0s}$  or  $f_{qs}$ ,  $f_{ds}$  and  $f_{0s}$  and transformation matrix is designated as  $K_s$ .
- $\omega = 0$ : stationary circuit variables referred to the stationary reference frame. The variables are referred to as  $f_{qd0s}^s$  or  $f_{qs}^s$ ,  $f_{ds}^s$  and  $f_{0s}^s$  and transformation matrix is designated as  $K_s^s$ .

# Commonly Used Reference Frames

- $\omega = \omega_r$ : stationary circuit variables referred to the reference frame fixed in the rotor. The variables are referred to as  $f_{qd0s}^r$  or  $f_{qs}^r$ ,  $f_{ds}^r$  and  $f_{0s}^r$  and transformation matrix is designated as  $K_s^r$ .
- $\omega = \omega_e$ : stationary circuit variables referred to the synchronously rotating reference frame. The variables are referred to as  $f_{qd0s}^e$  or  $f_{qs}^e$ ,  $f_{ds}^e$  and  $f_{0s}^e$  and transformation matrix is designated as  $K_s^e$ .

# Commonly Used Reference Frames

## ■ Representation

$f_{qd0s}^s$  → Stationary reference frame  
 $f_{qd0s}^s$  → q-d axes of stator variables

$f_{qd0s}^r$  → Reference frame fixed on the rotor with speed of  $\omega_r$   
 $f_{qd0s}^r$  → q-d axes of stator variables,  $\theta_r = \int_0^t \omega_r(t) dt$

$f_{qd0s}^e$  → Synchronously rotating reference frame  
 $f_{qd0s}^e$  → q-d axes of stator variables,  $\theta_e = \int_0^t \omega_e(t) dt$

# Transformation of a Balanced Set

- Consider a 3-phase circuit which is excited by a balanced 3-phase voltage set. Assume the balanced set is a set of equal amplitude sinusoidal quantities which are displaced by  $120^\circ$ .

$$f_{as} = \sqrt{2} f_s \cos \theta_{ef}$$

$$f_{as} + f_{bs} + f_{cs} = 0 \text{ (balanced set)}$$

$$f_{bs} = \sqrt{2} f_s \cos\left(\theta_{ef} - \frac{2\pi}{3}\right)$$

$$\theta_{ef} = \int_0^t \omega_e(t) dt + \theta_{ef}(0)$$

$$f_{cs} = \sqrt{2} f_s \cos\left(\theta_{ef} + \frac{2\pi}{3}\right)$$

- $\theta_{ef}$ : Angular position of each electrical variable (voltage, current, and flux linkage) is  $\theta_{ef}$  with the f subscript used to denote the specific electrical variable.



# Transformation of a Balanced Set

- $\theta_e$ : Angular position of the synchronously rotating reference frame is  $\theta_e$ .
- $\theta_e$  and  $\theta_{ef}$  differ only in the zero position  $\theta_e(0)$  and  $\theta_{ef}(0)$ , since each has the same angular velocity of  $\omega_e$ .
- $f_{as}$ ,  $f_{bs}$  and  $f_{cs}$  can be transformed to the arbitrary reference frame,

$$\bar{f}_{qd0s} = \bar{\mathbf{K}}_s \bar{f}_{abcs}$$

# Transformation of a Balanced Set

- After transformation, we will have,

$$f_{qs} = \sqrt{2} f_s \cos(\theta_{ef} - \theta)$$

$$f_{ds} = -\sqrt{2} f_s \sin(\theta_{ef} - \theta)$$

$$f_{0s} = 0$$

- $qs$  and  $ds$  variables form a balanced 2-phase set in all reference frames except when  $\omega = \omega_e$ ,

$$f_{qs}^e = \sqrt{2} f_s \cos[\theta_{ef}(0) - \theta_e(0)]$$

$$f_{ds}^e = -\sqrt{2} f_s \sin[\theta_{ef}(0) - \theta_e(0)]$$

- In  $qs^e$  and  $ds^e$  reference frame, sinusoidal quantities appear as constant dc quantities.

# Balanced Steady-State Phasor Relationships

- For balanced steady-state conditions  $\omega_e$  is constant and sinusoidal quantities can be represented as phasor variables.

$$F_{as} = \sqrt{2}F_s \cos[\omega_e t + \theta_{ef}(0)] = \text{Re}\left[\sqrt{2}F_s e^{j\theta_{ef}(0)} e^{j\omega_e t}\right]$$

$$F_{bs} = \sqrt{2}F_s \cos\left[\omega_e t + \theta_{ef}(0) - \frac{2\pi}{3}\right] = \text{Re}\left[\sqrt{2}F_s e^{j\left(\theta_{ef}(0) - \frac{2\pi}{3}\right)} e^{j\omega_e t}\right]$$

$$F_{cs} = \sqrt{2}F_s \cos\left[\omega_e t + \theta_{ef}(0) + \frac{2\pi}{3}\right] = \text{Re}\left[\sqrt{2}F_s e^{j\left(\theta_{ef}(0) + \frac{2\pi}{3}\right)} e^{j\omega_e t}\right]$$

# Balanced Steady-State Phasor Relationships

- Balanced steady-state qs-ds variables are,

$$\begin{aligned} F_{qs} &= \sqrt{2}F_s \cos\left[(\omega_e - \omega)t + \theta_{ef}(0) - \theta(0)\right] \\ &= \text{Re}\left[\sqrt{2}F_s e^{j(\theta_{ef}(0) - \theta(0))} e^{j(\omega_e - \omega)t}\right] \end{aligned}$$

$$\begin{aligned} F_{ds} &= -\sqrt{2}F_s \sin\left[(\omega_e - \omega)t + \theta_{ef}(0) - \theta(0)\right] \\ &= \text{Re}\left[j\sqrt{2}F_s e^{j(\theta_{ef}(0) - \theta(0))} e^{j(\omega_e - \omega)t}\right] \end{aligned}$$

- $f_{as}$  phasor can be expressed as

$$\tilde{F}_{as} = F_s e^{j\theta_{ef}(0)}$$

# Balanced Steady-State Phasor Relationships

- For arbitrary reference frame ( $\omega \neq \omega_e$ ),

$$\tilde{F}_{qs} = F_s e^{j(\theta_{ef}(0) - \theta(0))}, \quad \tilde{F}_{ds} = j\tilde{F}_{qs}$$

- Selecting  $\theta(0)=0$ ,

$$\tilde{F}_{as} = \tilde{F}_{qs}$$

- Thus, in all asynchronously rotating reference frame ( $\omega \neq \omega_e$ ) with  $\theta(0)=0$ , the phasor representing the  $as$  variables is equal to the phasor representing the  $qs$  variables.

# Balanced Steady-State Phasor Relationships

- In the synchronously rotating reference frame  $\omega = \omega_e$ ,  $F_{qs}^e$  and  $F_{ds}^e$  can be expressed as

$$F_{qs}^e = \text{Re} \left[ \sqrt{2} F_s e^{j(\theta_{ef}(0) - \theta(0))} \right]$$

$$F_{ds}^e = \text{Re} \left[ j \sqrt{2} F_s e^{j(\theta_{ef}(0) - \theta(0))} \right]$$

- Let  $\theta_e(0) = 0$ , then


$$F_{qs}^e = \sqrt{2} F_s \cos(\theta_{ef}(0)), \quad F_{ds}^e = -\sqrt{2} F_s \sin(\theta_{ef}(0))$$

$$\sqrt{2} \tilde{F}_{as} = F_{qs}^e - j F_{ds}^e$$

$$\text{since, } \tilde{F}_{as} = F_s e^{j(\theta_{ef}(0))} = F_s \cos(\theta_{ef}(0)) + j F_s \sin(\theta_{ef}(0))$$

# Balanced Steady-State Phasor Relationships

- Consider the stator winding of a symmetrical induction machine.



- Assume the stator winding is excited by a balanced 3-phase sinusoidal voltage set.

# Balanced Steady-State Phasor Relationships

- For phase  $a_s$ , we will have  $\left(p = \frac{d}{dt}\right)$

$$V_{as} = r_s i_{as} + L_s p i_{as} + M p i_{bs} + M p i_{cs}$$

- For balanced conditions

$$V_{as} + V_{bs} + V_{cs} = 0, \quad i_{as} + i_{bs} + i_{cs} = 0$$

$$M p i_{as} = -M p (i_{bs} + i_{cs}), \quad V_{as} = r_s i_{as} + (L_s - M) p i_{as}$$

- For steady-state conditions,  $p = j\omega_e$

$$\tilde{V}_{as} = r_s \tilde{I}_{as} + [(L_s - M) j\omega_e] \tilde{I}_{as}$$



# Balanced Steady-State Phasor Relationships

- $qs$  and  $ds$  voltage equations in the arbitrary reference frame can be written as

$$V_{qs} = r_s i_{qs} + \omega \lambda_{ds} + p \lambda_{qs}$$

$$V_{ds} = r_s i_{ds} - \omega \lambda_{qs} + p \lambda_{ds}$$

$$\lambda_{qs} = (L_s - M) i_{qs}, \quad \lambda_{ds} = (L_s - M) i_{ds}$$

- Let  $\omega = \omega_e$ , then

$$V_{qs}^e = r_s i_{qs}^e + \omega_e \lambda_{ds}^e + p \lambda_{qs}^e$$

$$V_{ds}^e = r_s i_{ds}^e - \omega_e \lambda_{qs}^e + p \lambda_{ds}^e$$

$$\lambda_{qs}^e = (L_s - M) i_{qs}^e, \quad \lambda_{ds}^e = (L_s - M) i_{ds}^e$$

# Balanced Steady-State Phasor Relationships

- For balanced steady-state conditions, the variables in the synchronously rotating reference frame are constants, therefore  $p\lambda_{qs}^e$  and  $p\lambda_{ds}^e$  are zero. Therefore, the above can be expressed as

$$V_{qs}^e = r_s I_{qs}^e + \omega_e (L_s - M) I_{ds}^e$$

$$V_{ds}^e = r_s I_{ds}^e - \omega_e (L_s - M) I_{qs}^e$$

- Recall  $\sqrt{2}\tilde{F}_{as} = F_{qs}^e - jF_{ds}^e$
- Thus,  $\sqrt{2}\tilde{V}_{as} = V_{qs}^e - jV_{ds}^e$

# Balanced Steady-State Phasor Relationships

$$\sqrt{2}\tilde{V}_{as} = r_s I^e_{qs} + \omega_e (L_s - M) I^e_{ds} - j \left[ r_s I^e_{ds} + \omega_e (L_s - M) I^e_{qs} \right]$$

■ Now


$$\sqrt{2}\tilde{I}_{as} = I^e_{qs} - jI^e_{ds}$$

$$j\sqrt{2}\tilde{I}_{as} = I^e_{ds} + jI^e_{qs}$$


■ Substituting in the above equation, we will have

$$\tilde{V}_{as} = \left[ r_s + j\omega_e (L_s - M) \right] \tilde{I}_{as}$$

# ■ qd · Transformation to Shunt Capacitances



## ■ $qd$ Transformation to Shunt Capacitances



# Variables Observed From Several Frames of Reference

- Suppose Following Voltages Applied to 3 Phase Wye-Connected RL Circuit:

$$\blacktriangleright v_{as} = \sqrt{2}V_s \cos \omega_e t$$

$$\blacktriangleright v_{bs} = \sqrt{2}V_s \cos \left( \omega_e t - \frac{2\pi}{3} \right)$$

$$\blacktriangleright v_{cs} = \sqrt{2}V_s \cos \left( \omega_e t + \frac{2\pi}{3} \right)$$

# Variables Observed From Several Frames of Reference

## ■ Using Basic Circuit Analysis Techniques

$$\blacktriangleright i_{as} = \frac{\sqrt{2}V_s}{|Z_s|} [-e^{-t/\tau} \cos \alpha + \cos(\omega_e t - \alpha)]$$

$$\blacktriangleright i_{bs} = \frac{\sqrt{2}V_s}{|Z_s|} \left[ -e^{-t/\tau} \cos\left(\alpha + \frac{2\pi}{3}\right) + \cos\left(\omega_e t - \alpha - \frac{2\pi}{3}\right) \right]$$

$$\blacktriangleright i_{cs} = \frac{\sqrt{2}V_s}{|Z_s|} \left[ -e^{-t/\tau} \cos\left(\alpha - \frac{2\pi}{3}\right) + \cos\left(\omega_e t - \alpha + \frac{2\pi}{3}\right) \right]$$

$$\blacktriangleright Z_s = r_s + j\omega_e L_s$$

$$\blacktriangleright \tau = \frac{L_s}{r_s}$$

$$\blacktriangleright \alpha = \tan^{-1} \frac{\omega_e L_s}{r_s}$$

# Variables Observed From Several Frames of Reference


- Transforming to the Synchronous Reference Frame:

$$\begin{aligned} \text{➤ } i_{qs} &= \frac{\sqrt{2}V_s}{|Z_s|} \left\{ -e^{-t/\tau} \cos(\omega t - \alpha) \right. \\ &\quad \left. + \cos[(\omega_e - \omega)t - \alpha] \right\} \\ \text{➤ } i_{ds} &= \frac{\sqrt{2}V_s}{|Z_s|} \left\{ -e^{-t/\tau} \sin(\omega t - \alpha) \right. \\ &\quad \left. - \sin[(\omega_e - \omega)t - \alpha] \right\} \end{aligned}$$




# Variables Observed From Several Frames of Reference

## ■ In Stationary Reference Frame




**Figure 3.10-1** Variables of a stationary 3-phase system in the stationary reference frame.

# Variables Observed From Several Frames of Reference




## ■ In Synchronous Reference Frame



# Variables Observed From Several Frames of Reference

## ■ In Strange Reference Frame



**Figure 3.10-3** Variables of a stationary 3-phase system. First with  $\omega = -\omega_e$ , then  $\omega$  is stepped to zero followed by a ramp change in reference frame speed to  $\omega = \omega_e$ .

# Transformation Between Reference Frames

- To transform the variables from  $\underline{x}$  to  $\underline{y}$  reference frame :

$$\mathbf{f}_{qd0s}^y = {}^x\mathbf{K}^y \mathbf{f}_{qd0s}^x$$

$$\mathbf{f}_{qd0s}^x = \mathbf{K}_s^x \mathbf{f}_{abcs}$$

$$\mathbf{f}_{qd0s}^y = {}^x\mathbf{K}^y \mathbf{K}_s^x \mathbf{f}_{abcs}$$

$$\mathbf{f}_{qd0s}^y = \mathbf{K}_s^y \mathbf{f}_{abcs}$$

$${}^x\mathbf{K}^y \mathbf{K}_s^x = \mathbf{K}_s^y$$

$${}^x\mathbf{K}^y = \mathbf{K}_s^y (\mathbf{K}_s^x)^{-1}$$


# Transformation Between Reference Frames

$$\Rightarrow {}^x\mathbf{K}^y = \begin{bmatrix} \cos(\theta_y - \theta_x) & -\sin(\theta_y - \theta_x) & 0 \\ \sin(\theta_y - \theta_x) & \cos(\theta_y - \theta_x) & 0 \\ 0 & 0 & 1 \end{bmatrix}$$

$$({}^x\mathbf{K}^y)^{-1} = ({}^x\mathbf{K}^y)^T$$

- For example:

$$\begin{bmatrix} i_q \\ i_d \end{bmatrix} = \begin{bmatrix} \cos\theta & -\sin\theta \\ \sin\theta & \cos\theta \end{bmatrix} \begin{bmatrix} i_q^s \\ i_d^s \end{bmatrix}$$



# Space Vectors

- Three-phase voltages

$$v_{An}(t) + v_{Bn}(t) + v_{Cn}(t) = 0$$

- Two-phase voltages

$$\begin{bmatrix} v_{\alpha}(t) \\ v_{\beta}(t) \end{bmatrix} = \frac{2}{3} \begin{bmatrix} \cos 0 & \cos \frac{2\pi}{3} & \cos \frac{4\pi}{3} \\ \sin 0 & \sin \frac{2\pi}{3} & \sin \frac{4\pi}{3} \end{bmatrix} \begin{bmatrix} v_{An}(t) \\ v_{Bn}(t) \\ v_{Cn}(t) \end{bmatrix} = \frac{2}{3} \begin{bmatrix} 1 & -\frac{1}{2} & -\frac{1}{2} \\ 0 & \frac{\sqrt{3}}{2} & -\frac{\sqrt{3}}{2} \end{bmatrix} \begin{bmatrix} v_{An}(t) \\ v_{Bn}(t) \\ v_{Cn}(t) \end{bmatrix}$$

- Space vector representation

$$\vec{V}(t) = v_{\alpha}(t) + j v_{\beta}(t)$$

$$\vec{V}(t) = \frac{2}{3} \left[ v_{An}(t) e^{j0} + v_{Bn}(t) e^{j2\pi/3} + v_{Cn}(t) e^{j4\pi/3} \right]$$

where

$$|\vec{V}| = \sqrt{V_{\alpha}^2 + V_{\beta}^2}$$

$$\alpha = \tan^{-1} \left( \frac{V_{\beta}}{V_{\alpha}} \right) = \omega_s t = 2\pi f_s t$$

(where,  $f_s$  = fundamental frequency)

